	Туре	L #	Hits	Search Text	DBs
1	BRS	L51	2375	<pre>(leadframe (lead adj frame)) and ((power near1 ring) ring)</pre>	USPAT; US-PGPUB; EPO; JPO; DERWENT
2	BRS	L52	1625	51 and (wire wiring)	USPAT; US-PGPUB; EPO; JPO; DERWENT
3	BRS	L53	2375	<pre>(leadframe (lead adj frame)) and ((power nearl ring) ring)</pre>	USPAT; US-PGPUB; EPO; JPO; DERWENT
4	BRS	L54	18	(leadframe (lead adj frame)) and (power nearl ring)	USPAT; US-PGPUB; EPO; JPO; DERWENT
5	BRS	L55	9	("4891687"   "4975761"   "4994897"   "5012386"   "5105259"   "5138430"   "5172213"   "5227662"   "5278446").PN.	USPAT
6	BRS	L56	0	6326678.URPN.	USPAT
7	BRS	L57	0	6285075.URPN.	USPAT
8	BRS	L58	7	("4862245"   "4975761"   "5172213"   "5367196"   "5504372"   "5757070"   "5895966").PN.	USPAT
9	BRS	L59	11	5757070.URPN.	USPAT
10	BRS	L60	16	("3825803"   "3996447"   "5229918"   "5278446"   "5345106"   "5381042"   "5430331"   "5596231"   "5666003"   "5705851"   "5723899"   "5757070"   "5790378"   "5801435"   "5895966"   "5936303").PN.	USPAT
11	BRS	L61	1	5936303.URPN.	USPAT
12	BRS	L62	3	("4891687"   "5723899"   "5757070").PN.	USPAT
13	BRS	L63	13	5723899.URPN.	USPAT
14	BRS	L64	13	5723899.URPN.	USPAT
15	BRS	L65	8	("5121300"   "5168368"   "5235207"   "5309019"   "5420758"   "5455454"   "5498901"   "5543657").PN.	USPAT
16	BRS	L66	3	6064115.URPN.	USPAT
17	BRS	L67	3	("4891687"   "5723899"   "5757070").PN.	USPAT

05/20/2002, EAST Version: 1.03.0002

	Time Stamp	Comments	Error Definition	Err ors
1	2002/05/20 13:23			0
2	2002/05/20 13:22			0
3	2002/05/20 13:24			0
4	2002/05/20 13:24			0
5	2002/05/20 13:28			0
6	2002/05/20 13:28	•••••••••••		0
7	2002/05/20 13:29			0
8	2002/05/20 13:29			0
9	2002/05/20 13:30			0
10	2002/05/20 13:32			Ο
11	2002/05/20 13:33		•	0
12	2002/05/20 13:33			0
13	2002/05/20 13:35			0
14	2002/05/20 13:37		•	0
15	2002/05/20 13:37			О
16	2002/05/20 13:38			0
17	2002/05/20 13:39			0

	Туре	L #	Hits	Search Text	DBs
18	BRS	L68	1	5936303.URPN.	USPAT
19	BRS	L69	11	5757070.URPN.	USPAT
20	BRS	L70	11	5757070.URPN.	USPAT
21	BRS	L71	4	("5196725"   "5365409"   "5455453"   "5633529").PN.	USPAT

	Time Stamp	Comments	Error Definition	Err
18	2002/05/20 13:39			0
19	2002/05/20 13:39	***************************************	• • • • • • • • • • • • • • • • • • • •	0
20	2002/05/20 13:39			0
21	2002/05/20 13:39		***************************************	0

	Туре	L #	Hits	Search Text	DBs	
22	BRS	L72	1258	(leadframe (lead adj frame)) and ring and semiconductor and (wire wiring)	USPAT; US-PGPUB; EPO; JPO; DERWENT	
23	BRS	L73	311	72 and ((die nearl pad) (die adj paddle))	USPAT; US-PGPUB; EPO; JPO; DERWENT	
24	BRS	L74	302	73 not 54	USPAT; US-PGPUB; EPO; JPO; DERWENT	
25	BRS	L75	49	74 and (tie near bar)	USPAT; US-PGPUB; EPO; JPO; DERWENT	
26	BRS	L76	4	6031281.URPN.	USPAT	
27	BRS	L77	9	("5045919"   "5296743"   "5302850"   "5359227"   "5457340"   "5684332"   "5780772"   "5859471"   "5869898").PN.	USPAT	

	Time Stamp	Comments	Error Definition	Err
22	2002/05/20 13:45			0
23	2002/05/20 13:49			0
24	2002/05/20 13:50		·	0
25	2002/05/20 13:50			0
26	2002/05/20 13:56			0
27	2002/05/20 13:56			Ο